



WINPOWER CORPORATION

Model FM12V4-L/3B Type 2
12.5 KW 15.6 KVA .8 P.F.
105°C Rise 3 Phase 60 HZ 4 Wire
Wiring Diagram IE-9666
Released 11-19-76

REF NO.	PART NO.	PART DESCRIPTION	QTY/REQ'D
1	3600-2	Bolt	3
2	G-6254-1	Drive End Bell	1
3	D-22	Bearing	1
4	G-6122	Fan	1
5	G-6299-18	Stator Assembly	1
5a	G-6259	Stator Electric	1
5b	G-6095-2	Stator Housing	1
6	G-6139	Field Pole	4
7	H-1128	Coil	4
8	S-2056-26	Key	1
9	G-6258-2	Rotor	1
10	G-6350	Rectifier	2
11	S-7513	Mounting Board Bracket	2
12	S-7618	Mounting Board	1
13	EE-1994	Current Transformer	1
14	EE-2200	Rectifier	1
15	D-16-1	Bearing	1
16	G-6253-1	Exciter End Bell	1
17	3599-3	Bolt	3
18	EE-1995	Choke	1
19	3590-2	Bolt	4
20	G-6351	Varistor Assembly	1
21	G-6264	Terminal Box	1
22	S-7617	Holddown Plate	1

PL-1714



